

0310457034/Cook
Roadway
LUST/Gen Reports

ROADWAY SERVICES, INC.

1077 GORGE BOULEVARD
P O BOX 88
AKRON, OH 44309-0088
(216) 384-8184

September 18, 1990

Mr. Ken Page
Leaking Underground Storage Tank Section
Division of Land Pollution Control
Illinois EPA
P. O. Box 19276
Springfield, Illinois 62794-9276



Re: LPC #0310000000--Cook County
Chicago Heights/Roadway Services, Inc.
200 Lincoln Highway
LUST Incident #891102

Dear Mr. Page:

In response to your August 23, 1990, communication requesting additional information regarding LUST Incident #891102, the following items are addressed.

1. A site map for the subject property has been included with this communication.
 - a. The location of the UST is identified on the site map.
 - b. The location of the product delivery lines are identified on the site map.
 - c. The location of all structures are identified on the site map.
 - d. Lincoln Highway is located approximately one-quarter mile north of the subject property. No sewers, adjacent to the subject property, have been identified.
 - e. The area of excavated soil is identified on the site map.
 - f. No soil borings, as related to this incident, were taken.
 - g. Confirmatory soil samples were collected from the floor and two sides of the excavation.
2. The specific geology of the subject area has not been identified; however, soil conditions appear to be primarily silts and clays. Depth to groundwater is approximately 20 feet. No groundwater was encountered during excavation activities.
3. Analytical results from soil samples collected in the excavation are enclosed. No groundwater samples were collected.



RECEIVED

OCT 1 1990

IEPA/DLPC

Mr. Ken Page
September 18, 1990
Page Two

4. Approximately 30 cubic yards of contaminated soil were excavated. All excavated soil was disposed of at CID landfill, Calumet City, Illinois.
5. Since July 17, 1989, the leak in the pipeline has been repaired, the excavation backfilled, and the area re-asphalted.
6. A tightness test of the system has not been conducted.
7. No additional activities, as related to this incident, are planned.

If you have any questions concerning this incident, please contact me at 216/258-2443.

Sincerely,


Roadway Services, Inc. for
Roadway Express, Inc.



Grant B. Wilk
Environmental Geologist

jmc/gbw2
Enclosures
cc: Messrs. J. C. Swart
Randy Avery (309)

BPM INDUSTRIES
1150 Junction Avenue - Schererville, Indiana 46375
1-219-322-2560 • 1-800-428-3311



WO #: 21-2396

Certified by: Patricia Date: 10/10/06


TENCO LABORATORIES

BPM INDUSTRIES

1150 Junction Avenue - Schererville, Indiana 46375

1-219-322-2560 • 1-800-428-3311

REPORT TO:
Phil Hough
ICEP
3468 Watling Rd
East Chicago IN 46312



Date: 7/20/89

Recd: 7/11/89

WO #: 21-2396

PROJECT ROADWAY EXPRESS

Laboratory Smp ID No.:	7956-9	7957-9	7958-9				
DESCRIPTION: —> (Unless otherwise noted; results in parts per billion - ppb) PARAMETERS: ↓	Floor 1A Dirty	1B Side Clean	1C Side Clean	Detection Limits			
Benzene	ND	ND	15.	5 ppb			
Ethyl Benzene	ND	ND	ND	5 ppb			
Toluene	ND	ND	ND	5 ppb			
Xylene	208.	39.	ND	15 ppb			
Acenaphthene	ND	ND	ND	1200 ppb			
Acenaphthylene	ND	ND	ND	660 ppb			
Anthracene	ND	ND	ND	660 ppb			
Benzo(a)anthracene	ND	ND	ND	8.7 ppb			
Benzo(a)pyrene	ND	ND	ND	15 ppb			
Benzo(b)fluoranthene	ND	ND	263.	12 ppb			
Benzo(ghi)perylene	ND	ND	ND	51 ppb			
Benzo(k)fluoranthene	ND	ND	ND	11 ppb			
Chrysene	ND	ND	ND	100 ppb			
Dibenzo(a,h)anthracene	ND	ND	ND	20 ppb			
Fluoranthene	ND	ND	107.	140 ppb			
Fluorene	ND	ND	ND	140 ppb			
Indeno(1,2,3-cd)pyrene	ND	ND	ND	29 ppb			

ND=Not Detected

BPM INDUSTRIES
1150 Junction Avenue - Schererville, Indiana 46375
1-219-322-2560 ● 1-800-428-3311



WO #: 21-2396

Certified by: Anthony De L. - 1.1.06



CHAIN OF CUSTODY FORM

SAMPLE #	DESCRIPTION	QUANTITY	DATE
B-1	Virgin material	1 qt	7/7/89
1A	Contaminated soil	1 qt	7/7/89
1B	↓	1 qt	7/7/89
1C		1 qt	7/7/89

Joe Poracky	<i>Joe Poracky</i>	7/7/89
name (print)	signature	date
Phil Hough	<i>Phil Hough</i>	7/10/89
name (print)	signature	date
GRETCHEN RUBLE	<i>Gretchen Ruble</i>	7/10/89
name (print)	signature	date

ANALYZE SAMPLES FOR: B-1 PCB Scan BTEX PNA ^{open} cup ^{Flt} ^{PA in} ⁶⁰⁴¹¹ ⁵⁰¹

LOCATION: ROADWAY EXPRESS 2000 LINCOLN HWY CHICAGO HEIGHTS, ILL 60411

ICEP PROJECT ID: #8006

1-A
1-B
1-C

BTEX
PNA's

